

Appendix VII


FIRE SAFETY CERTIFICATE

No: 177

Date: 27/05/21

Certified that the BIOP Sr.Sec.School, Kirandul (Name of the building or premises) at Kirandul (address) comprised of basement(s) and Ground floor + 01 (upper floor) owned /occupied by BIOP Sr. Sec. School, NMDC BIOM Kirandul, Distt : Dantewada, C.G. (Name of the Institution) have complied with the fire prevention and fire safety requirements in accordance with rule of State/ UT Fire Service Rules, and verified by the officers concerned of Fire Service on 27-05-2021 (Date of inspection) in the presence of Principal BIOP Senior Sec. School, Kirandul and Municipal Council, Kirandul /Fire (Name and address of the Manager/ Secretary or his representative) and that the building /premises is fit for occupancy with effect from 27.05.2021 for a period of 01(one) years in accordance with rule and subject to compliance of the conditions.

Issued on 27/05/2021 at Kirandul by


मुख्य नगर पालिका अधिकारी
नगर पालिका परिषद
किरंदुल

Signature with seal:

Name

: Mr Hunga Ram Gonde

Designation

: chite municipal of fire
Kirandul Dist Dant.

inspection Date :- 27/05/2021

To

The Principal

BIOP Sr.Sec.School.

Kirandul

(Name and address of the Institution)

ENDORSEMENT

The NO Objection Certificate issued by Fire Service stand cancelled and annulled due to _____

(reason to be recorded)